Will the repair of the Cairngorm Funicular Railway work (3)?

Description



Figure 2-6 Cracking at a pier 9 (refer defect 1)

Since the release of the COWI report on 11th December, which Highlands and Islands Enterprise had withheld for two years, Parkswatch has been able to start investigating the repair of funicular (see <u>here</u>) and (here). We have been uncovering new issues and questions on an almost daily basis. For example, Pier 9 (photo above) featured in my last post, but what I had not realised was that this pier is one of a number of piers, P5 – P13 inclusive, below Anchor Block 14 (AB14) which are on a steady gradient, i.e. there are no sudden changes in height, and where no ground work was proposed as part of the planning application:



Extract from Planning documents. Green squares indicate work where ground works are planned and include pier 14, an anchor block, but not the ten piers below.

Unfortunately we are unable to do a site visit at present and have been unable to check from photos if it is the only pier in that section that exhibits damage. If it is, then why is it in such poor condition? Above ground work was not included in the planning application to the Cairngorms National Park Authority and because of that it is not clear what superstructural repairs are include in the £16m repair to the funicular. Information about that is important for understanding what has gone wrong and why repairs are needed.

Following my first post on the repairs, parkswatch was contacted by someone who knows Cairn Gorm well, knew people who had been involved in construction work there and has expertise in rail tracks. He told me that about two years after the funicular was opened he had gone up to the Ptarmigan and became very aware of an increased level of noise as the train entered the tunnel. This is a classic sign of corrugated rails and he advised management at the time that if rail grinding wasn't carried out the problems would only get worse. Nothing happened.

The need for rail maintenance

Because of the interaction between the wheels on a train and the tracks themselves, rails become rippled/ corrugated, i.e. high and low spots. These, if they aren't repaired, get worse and lead to hairline cracks in the rails which only get bigger and can eventually lead to rail failure.

Corrugated rails also cause vibrations in the rails which in the case of the funicular may have been transmitted to the concrete crossheads, piers and foundations, causing damage to the structure and

also to the carriages themselves, making for an uncomfortable ride. The worse the corrugation, the worse the vibration.

On Friday 01/12/2017 the following announcement was made:-

Network Rail has unveiled three new grinding trains costing £36m, which we be deploy keep the track in good condition and provide passengers with a smooth, reliable journ

The multi-million pound trains, which remove small layers of metal from the railhead, investment for Network Rail route services who worked with industry partners Loram build and maintain the new, improved models.



Photo credit Network Rail

What, you may well ask, has that to do with the Cairngorm funicular? The answer is that corrugated rails occur on every rail track, including the funicular! Obviously such huge machinery is not necessary for funicular railways and there are small machines which, with a suitably qualified operator, are more appropriate.

The following extracts are from the Loram website, an American company who specialise in rail grinding equipment with a subsidiary Loram UK in Derby.

Extend the Life of Your Rail

Rail grinding is the cornerstone of virtually every railroad maintenance program. To maximize the life and value of rail assets, precision removal of fatigued metal, restoration of the rail head profile and removal of rail defects Loram's rail grinding solutions deliver substantial return on investment including:

- Extended rail life and track component life
- Improved wheel and rail interaction
- Prevention of premature rail failures and replacement
- Fuel savings
- Improved ride quality and passenger comfort default

After New

Year I contacted a company who carries out this kind of work and asked about inspection/maintenance times. The company recommended inspection of tracks about every six months and, if there is a problem with the rails, they then carry out rail grinding with a machine that can be used on one track at a time. It is not clear, how often, this had been done at Cairn Gorm but I have checked and it is done on funiculars in the Alps. I therefore sent a Freedom of Information request to HIE on Wednesday 06/01/2021 asking for details of maintenance to the track as well as the bogies.

Another problem caused by the wheels is wear and tear on the sides of one rail. The wheels on one side of the carriage bogies are double flanged as in the picture below:-



Image credit Brauer.co.uk

So not only are the wheels on that side wearing the top of the rail, but the sides as well. The funicular could have been not only running on rails which are corrugated on the top, but with wear and tear which would make it rattle from side to side as well! Any vibration and shaking will have been transferred into the piers and bases, and the taller the pier, the worse would be the effect on the foundations.

(NB the following photo appears to show the pier leaning more than it is, as you can see from the fence posts behind, but is the only one we have showing a taller pier)

Ja talle default Wate



This appears to be Pier 90 or 91

The COWI report says that it is the taller piers that are most affected. Another person who has contacted parkswatch has been a civil engineer and pointed out that a pier of this height should be wider at its base in order to support the weight higher up, that it should taper up to the highest point. But that would have meant that the preformed concrete outer shell at the bottom (no 5) would be larger and contain more re-inforcing than the next one up (No 4) and so on to the top. It could also have meant that the foundations for these taller piers would have to be bigger as well. It was said in the Audit Scotland report of 2009 that, because of the increasing costs, ways were being looked at to try and save money. Was using pre-formed shells of only one size one of the cost saving exercises and did this leave the taller pillars weaker than the short ones placing more stress on the foundations?

I have also been informed that the life span of a track is normally considered to be about 15-20years. Therefore it would appear that the train rails, even if rail grinding has been carried out, should need replacing, increasing the repair costs if that has not already been included in the price.

Our rail contact also mentioned:-

RESILIENT RAILWAY WHEELS

DESCRIPTION:

GMT specialise in providing high quality shock and noise reduction products to the railway industry, including Resilient Railway Wheels. These wheels can provide a significant reduction in noise and vibration through the use of rubber between the outer and inner metals.

Resilient Wheels offer other benefits such as lower operating costs. This is because they prevent unnecessary wear to the wheel and the track due to their elastic properties. There are three main types of Resilient Wheels available to order:

These are not used on the funicular despite their obvious benefits. Did the original design use this type of wheel but again, because of cost cutting measures, the specifications were changed to full steel wheels?

From all the information at present available for public scrutiny there does not appear to be any investigation as to why the funicular has failed, only how it is to be propped up so that it can be used again! Another FOI request has therefore been sent to HIE to understand the reasons for the structural failure. Surely it is imperative that the reasons why it's structural life has been less than one third of its design life are fully understood and reflected in the repair design? Our rail contact suspects that the propping up will only last about four years unless the faults that caused the failure are repaired!

HIE has a duty to answer these questions before proceeding further with the repairs. More will follow in my next post.

Category

1. Cairngorms

Tags

- 1. CNPA
- 2. funicular
- 3. HIE

Date Created

January 12, 2021 Author graham-garfoot

default watermark